




- Wanda-THINK
 - Baterie
 - Czujniki
 - Sierra Wireless GNSS Sensor EM7345 4G LTE
 - Karty graficzne
 - Karty sieciowe
 - 2x2 11b/g/n Wireless LAN M.2 Adapter
 - Intel(R) Ethernet Connection I217-V
 - Sierra Wireless EM7345 4G LTE
 - Klawiatury
 - Komputer
 - Kontrolery dźwięku, wideo i gier
 - Kontrolery IDE ATA/ATAPI
 - Kontrolery uniwersalnej magistrali szeregowej
 - Monitory
 - Mysz i inne urządzenia wskazujące
 - Procesory
 - SM Driver
 - Stacje dysków
 - Stacje dysków CD-ROM/DVD
 - Sterownik technologii pamięci
 - Urządzenia do obrazowania
 - Urządzenia systemowe
 - Urządzenia zabezpieczeń

Właściwości: Sierra Wireless EM7345 4G LTE

- Ogólne
- Sterownik
- Szczegóły**
- Zarządzanie energią



Sierra Wireless EM7345 4G LTE

Dostawca sterownika: Sierra Wireless

Data sterownika: 2016-01-06

Wersja sterownika: 1.5.1.1408

Podpis cyfrowy: Microsoft Windows Hardware Compatibility Publisher

- Szczegóły sterownika** Wyświetla informacje szczegółowe na temat plików sterownika.
- Aktualizuj sterownik... Aktualizuje oprogramowanie sterownika dla tego urządzenia.
- Przywróć sterownik Przywraca poprzednio zainstalowany sterownik, jeśli po zaktualizowaniu sterownika urządzenie nie działa.
- Wyłącz Wyłącza wybrane urządzenie
- Odinstaluj Odinstalowuje sterownik (zaawansowane).

OK Anuluj



- Connection Status
- Ping
- Trace Route
- IP Configuration
- Event Log

Profile name: aero2
Connection status: Not connected
Cause: WAN adapter is not ready.

Error code: 055

Recommended actions: Wireless WAN adapter is not ready. Please wait a few minutes and try again.

<< 1 of 2 >>

If the problem persists, contact your network administrator and provide the troubleshooting information below.

Adapter Details

Adapter name: Sierra Wireless EM7345 4G LTE
Adapter type: WAN
Adapter speed: 100.0 Mbps
Adapter status: Enabled
Connection Status: Not connected



Save As...

Close



- Connection Status
- Ping
- Trace Route
- IP Configuration
- Event Log

Profile name: aero2
Connection status: Not connected
Cause: WAN adapter is not ready.

Error code: 055

Recommended actions: The wireless WAN adapter is not properly inserted in the PC Card slot. Please try ejecting and reinserting the wireless WAN adapter.

<< 2 of 2 >>

If the problem persists, contact your network administrator and provide the troubleshooting information below.

System Information

System model: 20ASA0X2PB
BIOS version: J4ET62WW(1.62)
Operating system version: Windows 7, Service pack 1
Access connections version: 6.26.77

Save As...

Close

Access Connections

Location:

aero2

Connect

Switch to:

Basic

Connect to the Internet

Location Profiles

Tools


Mobile Hotspot

WiFi

Mobile Broadband

WIMAX

Other connections



Status

Not connected

[Help me fix this](#)

Service Type/Connection State

Bytes sent/received [Time]

Connect

1. Name of location profile:



aero2



2. Type of network connection:

Mobile Broadband

3. Choose the network adapter you want to use at this location:

Adapter name	Adapter status
  Sierra Wireless EM7345 4G LTE	Enabled 100/50 Mbps

Disconnect from the network when switching to a different location

Connect to LTE Service/HSDPA/GPRS network using Access Connections

"Automatic Settings" will fetch Mobile Broadband settings for known SIM cards and configures automatically while making Mobile Broadband connection. For unknown SIM cards please select "Custom Settings" and click on "Edit Settings" button to configure Mobile Broadband

Select Mobile Broadband Settings:

Custom Settings

Edit Settings

Network Settings

Known Mobile Broadband providers Settings:

Other

Custom service provider name: aero2

APN (Access Point Name): darmowy

User name:

Authentication option:

PAP

Prompt for authentication

Password:

Confirm password:

OK

Cancel

< Wstecz

Dalej >

Anuluj

Pomoc


Mobile Broadband radio off when disconnected

Access Connections

Location:

Connect

Switch to:

 Connect to the Internet

 Location Profiles

 Tools

 Mobile Hotspot

WiFi Mobile Broadband WiMAX Other connections

Access Connections



Connection Failed

Profile Name : aero2

Help Me Fix This...

Close

Service Type/Connection State	Status	Not connected	Help me fix this
Bytes sent/received [Time]			

Connect

Access Connections



Location:

aero2

Stop

Switch to:

Basic

Connect to the Internet

Location Profiles

Tools

Mobile Hotspot

WiFi

Mobile Broadband

WiMAX

Other connections



Status

Not connected

[Help me fix this](#)

Connect

Service Type/Connection State

Bytes sent/received [Time]

PL

(2:03)